

Cable Pin assignment (Intel's Guide)

2	4	6	8	10
VCC	P0-	P0+	GND	■
VCC	P1-	P1+	GND	OC
1	3	5	7	9

USB

2	4	6	8	10
TPA+	GND	TPB+	+12V	■
TPA-	GND	TPB-	+12V	GND
1	3	5	7	9


1394

1	2	3	4	5
+5V	-D	+D	GND	GND
+5V	-D	+D	■	GND
6	7	8	9	10

J1

1	2	3	4	5	6
VP	VG	TPB-	TPB+	TPA-	TPA+

J2




Cable For USB+1394

J1

2	4	6	8	10
+5V	-D	+D	GND	■
+5V	-D	+D	GND	GND
1	3	5	7	9

J2

2	4	6	8	10
TPA+	VG	TPB+	VP	■
TPA-	NC	TPB-	NC	NC
1	3	5	7	9



USB + 1394
BRACKET